

October 28th, 2011

MBI Water Solutions

My mother purchased an S-38 HydroPath Unit from you guys on 06/27/11. She had hard water in her faucets, showers, and water heater. Rudy came out and installed an S-38 HydroPath Unit and we did monthly water heater flushes for 3 months. The first month I was amazed to see how much white and reddish powder came out of the water heater! It plugged up the drain hose! The second flush had a bunch of powdery residue come out. By the 3rd month, the flush didn't dump much out. When my brother shined a flash-light up into the water heater, we could see shiny metal! My mother says there are a lot more suds to the soap and the ring in the bathtub is gone! My mother is so happy with the S-38 HydroPath Unit and would recommend it to anyone!

Thank you MBI for our S-38 HydroPath Unit!!!

Sincerely,

A handwritten signature in cursive script that reads "Jim Wilbanks". The signature is written in black ink and is positioned above the printed name and company information.

Jim Wilbanks
C & H Hardware, Inc.